

Hard Pipe Set Up with CO Monitor and 41 Series Filter

Compressor
3/4" drop
NPT Male Nipple




Reducer
3/4" to 1" F/F



1" Nipple
Threaded Both Ends

Monitor may connect to 1/4" NPT outlet or can connect to a tee off the gauge (connector kit included with monitor)

(For 41P6 - the sampling monitor will connect to one of the 3/8 NPT outlets or can connect to a tee off the gauge (connector kit included with monitor)



41P2 & COHP (COHP41P2)
1" NPT Inlet

1/4" NPT Outlet Female to Sampling Monitor
3/8" NPT Outlet Female to worker

1/4" Industrial Interchange (Hansen Compatible)



V15
3/8" Male NPT, 1/4" Female
Industrial Interchange QD Coupler



V17
1/4" Male Nipple
(included in 4696)



V13
Hose to Pipe Adaptor
(included in 4696)



4696
Starter Hose



F30
1/4" Industrial Interchange Fitting

1/4" Suptite



1/4" x 1/4" M/M
Threaded Nipple



V19
3/8" Male NPT
1/4" Female QD Suptite
Coupler Outlet



S19442
S19443 (Brass)
1/4" Male Nipple
Suptite



V12
Hose to Pipe
Adaptor



46915
Starter Hose



F32
1/4" Suptite Fitting



20BT
Breathing Tube

CC20 Series Hood



1/4" Schrader



1/4" x 1/4" M/M
Threaded Nipple



V18
1/4" Female QD
Schrader Outlet Coupler



S19432
1/4" Male Nipple
Schrader



V12
Hose to Pipe
Adaptor



46915
Starter Hose



F31
1/4" Schrader Fitting